



KeyTool Release Notes

KeyTool 1.1R29 2021-11-24

- Added a cleanup of HASP drivers to avoid conflict

KeyTool 1.1R26 2021-01-14

- Added a patch for the Windows 10 update (20H2)

KeyTool 1.1R25 2019-05-01

- Added support for Windows 10

KeyTool 1.1R24 2016-03-22

- Fixed some internal issues

KeyTool 1.1R22 2015-07-29

- Added FocusPC Analysis option
- Added FocusPC Inspection option
- Added FocusData option
- Added FocusControl option

KeyTool 1.1R21 2014-12-19

- Added PipeWIZARD™ 4.X Analysis to the list

KeyTool 1.1R20 2014-07-15

- Added warning message if Framework 4.0 is not installed

KeyTool 1.1R19 2014-04-10

- Added support for Windows 8

KeyTool 1.1R18

- Added UltraWaveLRT™ option
- Changed the TomoView™ 2.9+ option for TomoView 2.9–2.10

KeyTool 1.1R17

- Added the NDT SetupBuilder option

KeyTool 1.1R14

- Added the OmniPC™ option

KeyTool 1.1R12

- Added resources for simplified Chinese OS
- The XML file now contains the KeyTool version that created it

KeyTool 1.1R11

- Added the PipeWIZARD 32/128 option

KeyTool 1.1R10

- P18903: KeyTool launcher now correctly detects the .NET framework under a non-admin account

KeyTool 1.1R9

- Changed the AFiSiMo URL

KeyTool 1.1R8

- Renamed PipeWIZARD Scanner Control to Scanner Control
- Using an updated version of pass-key.dll

KeyTool 1.1R7

- The installer will now install the file "msvcr71.dll" if it is not present on the target system; this file is required by KeyTool

KeyTool 1.1R6

- Updated AFiSiMo activation to follow web-server changes (now asking for username, company, and key type)
- Now installing updated drivers (using command-line SRM installer version 5.75)

KeyTool 1.1R5

- P17061: Changed the ID for TomoView 2.9 Inspection and resurrected the PipeWIZARD WT Extension option
- P16142: Support for TomoView AFiSiMo

KeyTool 1.1R4

- Fixed TomoView 2.9 options
- Added options for QuickView™ 3.0
- Added option for Advanced Calculator 2.9

KeyTool 1.1R3

- P16140: Fixed the wise uninstallation bug when the install.log file is not present
- P15538: Fixed the Corrupt blast dll bug

KeyTool 1.1R2

- 8617: PipeWIZARD sortorder
- HASP driver is now installed correctly in silent mode

KeyTool 1.1R1

- TomoView Special 1 changed for TomoView Reserved 1
- Added the NDT SetupBuilder option