

Supporting Every Stage of the Geoscience and Mining Life Cycle

X-ray Fluorescence (XRF) | X-ray Diffraction (XRD) | Microscopy | Nondestructive Testing (NDT) Technology



and Mine Closure

- Soil, rock, and dust monitoring; site remediation; contamination mapping; waste and tailing classification, including acid-mine drainage (AMD)
- Mineralogical phase ID of waste and tails materials

- other wear surfaces
- Use remote video to visually inspect hard-toreach places
- Use microscopes to view welds at high magnification



www.olympus-ims.com