



KeyTool Release Notes

KeyTool 1.1R26 2021-01-14

- Added patch for the Windows 10 update (20H2).

KeyTool 1.1R25 2019-05-01

- Added support of Windows 10.

KeyTool 1.1R24 2016-03-22

- Fixed some internal issues.

KeyTool 1.1R22 2015-07-29

- Added FocusPC Analysis option.
- Added FocusPC Inspection option.
- Added FocusData option.
- Added FocusControl option.

KeyTool 1.1R21 2014-12-19

- Added Pipewizard 4.X Analysis to the list.

KeyTool 1.1R20 2014-07-15

- Added warning message if Framework 4.0 not installed.

KeyTool 1.1R19 2014-04-10

- Added support of Windows 8.

KeyTool 1.1R18

- Added option "UltraWaveLRT".

KeyTool 1.1R17

- Changed the option "TomoView 2.9+" for "TomoView 2.9 - 2.10".

KeyTool 1.1R15

- Added the Setup Builder option.

KeyTool 1.1R14

- Added the OmniPC option.

KeyTool 1.1R12

- Added resources for simplified Chinese OS.
- The XML file now contains the KeyTool version that created it.

KeyTool 1.1R11

- Added the option PipeWIZARD 32/128.

KeyTool 1.1R10

- P18903: KeyTool launcher now detects correctly the .NET framework under a non-admin account.

KeyTool 1.1R9

- Changed the AFiSiMo URL.

KeyTool 1.1R8

- Renamed "PipeWIZARD Scanner Control" to "Scanner Control".
- Using an updated version of pass-key.dll.

KeyTool 1.1R7

- The installer will now install the file "msvcr71.dll" if it's not present on the target system. This file is required by KeyTool.

KeyTool 1.1R6

- Updated AFiSiMo activation to follow web-server changes (now asking for user name, company and key type).
- Now installing updated drivers (using command-line SRM installer version 5.75).

KeyTool 1.1R5

- P17061: Changed the ID for TomoView 2.9 Inspection and resurrected the option PipeWizard WT Extension.
- P16142: Support for TomoView AFiSiMo.

KeyTool 1.1R4

- Fixed TomoView 2.9 options.
- Added options for QuickView 3.0.
- Added option for Advanced Calculator 2.9.

KeyTool 1.1R3

- P16140: Fixed the wise uninstallation bug when the install.log file is not present.
- P15538: Fixed the "Corrupt blast dll" bug.

KeyTool 1.1R2

- 8617: PipeWizard sortorder.
- HASP driver is now installed correctly in silent mode.

KeyTool 1.1R1

- "TomoView Special 1" changed for "TomoView Reserved 1".